



Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




***CAUTION:** If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler




*CAUTION: If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.




Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)

Parts – Mini Cheese Corn Tumbler



***CAUTION:** If supply cord is damaged, it must be replaced by Gold Medal Products Co., its service agent, or similarly qualified persons in order to avoid a hazard.



Item	Part No.	Description
1	49656	Glide 1" (x2)
2	89129	Hex Nut #8-32 (x2)
3	18710	Drive Bar Assembly
4	17543	Tumbler Base
5	87163	Strain Relief
6	22038	Lead-In Cord, 15 amp (Domestic)
	42369	Power Supply Cord (Export)
7	49045	Motor 120V (Domestic)
	49045EX	Motor 230V (Export)
8	42532	Switch, DPST Rocker
9	17544	Motor Cover
10	17542	Plastic Tub
11	17547	Lid (Not Pictured)