
## Parts & Accessories Diagram HBH550-CCC


**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



Harmiton Beach 4421 Waterfront Drive Glen Allen, VA 23060Request Number:DOC7433Revision Date:2/8/2017Approved by:DOC7433Glen Allen, VA 23060Issue Code(s):Page:1 of 3Document #:540047000Rev:D	Liousitten Decel	Revision Description: Show new reset switch CARE part number.							
Glen Allen, VA 23060 Issue Code(s): Page: 1 of 3 Document #: 540047000 Rev: D	Hamilton Beach 4421 Waterfront Drive	Request Number:	DOC7433	Revision Date:		2/8/2017	Approved by:	DOC7433	
	Glen Allen, VA 23060	Issue Code(s):		Page:	1 of 3	Document #:	540047000	Rev:	D

## Parts & Accessories Diagram HBH550-CCC

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




\*\*Cutter Assembly Includes: Blade, Lock Washer, Hex Nut, Drive Coupling Attachment and Cutter Bearing Assembly.

Revision Description: Show new reset switch CARE part number.	Show new reset switch CARE part number.						
Hamilton Beach 4421 Waterfront DriveRequest Number:DOC7433Revision Date:2/8/2017Approved	y: DOC74	DOC7433					
Glen Allen, VA 23060 Issue Code(s): Page: 2 of 3 Document #: 5400470	<b>)0</b> Rev:	D					

## Parts & Accessories Diagram HBH550-CCC

PROPRIETARY RIGHTS NOTICE This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.





## Notes:

\*Complete Container includes: Cutter Assembly, Container, Lid and Filler Cap

Harming Deach 4421 Waterfront DriveRequest Number:DOC7433Revision Date:2/8/2017Approved by:DOC7433Glen Allen, VA 23060Issue Code(s):Page:3 of 3Document #:540047000Rev:D	Liona	itter Beach	Revision Description: Show new reset switch CARE part number.							
Glen Allen, VA 23060 Issue Code(s): Page: 3 of 3 Document #: 540047000 Rev: D	Hamilton Beach 4421 Waterfront Drive		Request Number:	DOC7433	Revision Date:		2/8/2017	Approved by:	DOC7433	
	Glen A	Allen, VA 23060	Issue Code(s):		Page:	3 of 3	Document #:	540047000	Rev:	D