

## Technical Bulletin

TB: US201502RA

---

**Subject:** Correct Motor Identification

**Models:** Turbofan Models E32D5

---

**Description of Change:** It has come to our attention that incorrect motors are being ordered for replacement. The following is meant as a clarification of the proper motor to be ordered based on the serial number of the machine and motor characteristics.

**M237548** – Kit for any E32D5 up to serial number 706748 which only has 4 wires



If the machine already has a motor with 7 wires and this connector they can replace just the motor with the M237335.



**M235625** - For any E32D5 from 708232 – 759468 this motor has 8 wires and is manufactured by Fir.



**M237335** - For any E32D5 from 759469.  
This is a Hanning motor with 7 wires.

