
## Parts and Accesories Diagram Model HBH850-CE

PROPRIETARY RIGHTS NOTICE This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




**NOTE:** Power Switch 990086300 and Circuit Breaker 990079200 work for Series A-K but not with Series L+ or with new upper housing 990154810. Series A-K please reference Tech. Services for how to jumper the board with the removal of the front power button.

Hamilton Beach 4421 Waterfront Drive	Revision Description	Update Upper Housing							
	Request Number:	DOC7420	Revision Date		2/2/2017	Approved by:	DOC7420		
Glen Allen, VA 23060	Issue Code(s):		Page:	1 of 4	Document #:	510024900	Rev:	L	

## Parts and Accesories Diagram Model HBH850-CE


PROPRIETARY RIGHTS NOTICE This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



<b>Hamilton Beach</b> 4421 Waterfront Drive Glen Allen, VA 23060	Revision Description	vision Description: Update Upper Housing						
	Request Number:	DOC7420	Revisio	n Date:	2/2/2017	Approved by:	DOC7420	
	Issue Code(s):	_	Page:	2 of 4	Document #:	510024900	Rev:	L

### Parts and Accesories Diagram Model HBH850-CE

PROPRIETARY RIGHTS NOTICE and an all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



#### Notes:


- \*Complete Container Includes: Cutter Assembly, Container, Lid and Filler Cap
- \*\*Cutter Assembly Includes: Blade, Lock Washer, Hex Nut, Drive Coupling Attachment and Cutter Bearing Assembly.

Hamilton Beach 4421 Waterfront Drive Glen Allen, VA 23060	Revision Description:	Update Upper Housing						,
	Request Number:	DOC7420	Revision Date:		2/2/2017	Approved by:	DOC7420	
	Issue Code(s):		Page:	3 of 4	Document #:	510024900	Rev:	L

# <u>Parts and Accesories Diagram</u> <u>Model HBH850-CE</u>


PROPRIETARY RIGHTS NOTICE This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.

### **Accessories**



48oz Container Complete\* 6126-600

Container Washer BCR100



Hamilton Beach 4421 Waterfront Drive Glen Allen, VA 23060	Revision Description	n: Update Upper	Update Upper Housing					
	Request Number:	DOC7420	Revision Date:		2/2/2017	Approved by:	DOC7420	
	Issue Code(s):		Page:	4 of 4	Document #:	510024900	Rev:	L