
Replacement Parts Diagram HMD400-CE (Series A)

PROPRIETARY RIGHTS NOTICE and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




* Factory Assembled, Not Available As Separate Pieces

Hamilton Booch	Revision Description	n: Changed core	Changed cordset part number					
Hamilton Beach 4421 Waterfront Drive	Request Number:	CME-2734	Revision Date:		11/03/09	Approved by:	CME-2734	
Glen Allen, VA 23060	Issue Code(s):	CS, SP	Page:	1 of 3	Document #:	510012500	Rev:	E

Replacement Parts Diagram HMD400-CE (Series A)

PROPRIETARY RIGHTS NOTICE This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




Hamilton Beach 4421 Waterfront Drive Glen Allen, VA 23060	Revision Descripti	Revision Description: Changed cordset part number						
	Request Number:	CME-2734	Revision Date:		11/03/09	Approved by:	CME-2734	
	Issue Code(s):	CS, SP	Page:	2 of 3	Document #:	510012500	Rev:	E

Replacement Parts Diagram

HMD400-CE (Series A)

PROPRIETARY RIGHTS NOTICE and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



RFI Board 990050500

Hamilton Beach 4421 Waterfront Drive Glen Allen, VA 23060	Revision Description	on: Changed core	Changed cordset part number					
	Request Number:	CME-2734	Revision Date:		11/03/09	Approved by:	CME-2734	
	Issue Code(s):	CS, SP	Page:	3 of 3	Document #:	510012500	Rev:	E